

TG 100



LCC 100 Software

Configuration software for transmitters sensor

(monostats, class 50 and class 100) with RS 232 cable :
you can configure the measuring ranges and units, the
analog output...



Class 2 Power Supply

Class 2 Power supply : mounting brackets or DIN rail, 230
Vac input voltage, 24 Vac or Vdc output voltage, 3 VA ou 12
W power.



Stainless Steel Clamp

BF : Clamp for temperature transmitter \varnothing 6 or 8 mm.

BF-6 : Stainless steel clamp for Pitot tube \varnothing 3 and 6 mm.

BF-8 : Stainless steel clamp for Pitot tube \varnothing 8 mm.



Stainless Steel

Stainless steel sliding connections with a teflon nipple.
1/4 cylindrical gas threading.



Pt 100 & Thermocouple K Probes

► Wide range of Pt 100 and thermocouple K probes :
head, wire, sheathed...